

Building and Van Engineer

20 February 2014

VAN

Bi-Annual Engine Service (West Service)

Chassis Lube

Re-fastened floor grates

Narrowed jack plates and added handles

Fixed hydraulic leak at right front jack

Calibrated all three audiometers

Driver side tonometer repaired and recalibrated

Passenger side tonometer cleaned and functioning normally

Windshield curtains cleaned and lined with light-blocking fabric

New light-blocking curtain made and hung behind passenger seat/table

-Many Thanks to Jim Palacio for his sewing skills!!

BUILDING

Re-negotiated MOA for sharing space with EGRC and Float

Painted floor

Painted yellow safety path and staging area for EGRC

ISSUES

Cage mezzanine to isolate eyeglasses

Finish latticework on mezzanine

Plumb compressor

Wire compressor / extra 120 VAC outlets

Some storage compartment latches not engaging

Clean / descale wheels and hubs

WISH LIST

Clean & adjust Titmus machines as spares.

Install new exit sign / emergency light at van-side door.

Wire entrance doors to sound bell when opened.

Install ventilators on roof.

Light switch on opposite wall.